0060



Michael O. Leavitt Governor Ted Stewart **Executive Director** James W. Carter

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) Division Director 801-538-5319 (TDD)

September 23, 1993

Mr. Wendell Owen Co-Op Mining Company P.O. Box 1245 Huntington, Utah 84528

Re: D-4aD and D-13D Design, NOVs #N93-35-5-1 and N93-35-6-1, Co-Op

Mining Company, Bear Canyon Mine, ACT/015/025-93K, Folder #2, Emery

County, Utah

Dear Mr. Owen:

The Division has reviewed the abatement plans for violations #N93-35-5-1 and N93-35-6-1. The proposal to use an open ditch will hopefully prevent failures due to clogging. However, there is no mention of headwall associated with ditch D-4aD. Therefore, please provide the necessary information to delineate the inlet and outlet to ditch D-4aD and describe how coal will be prevented from blocking this inlet and also how excessive erosion and/or deposition of coal material will be controlled at the outlet. Please submit this information by October 7, 1993.

If you have any questions, please call me or Tom Munson.

Sincerely,

Pamela Grubaugh/Littig

Permit Supervisor

cc: Susan White

